

JUROP PUMP TROUBLESHOOTING

KOBLEM: THE PUMP IS OVERHEATING

CAUSE

- · Faulty lubrication
- · Missing Oil
- · RPMs too high
- · Operating time too long at too high vacuum rate
- · Clogged filters on the air injection system
- Exhaust port/Check valve partly clogged
- · Insufficient diameter of hoses

REMEDY

- · Check the oil pump
- · Fill up the oil tank
- Reduce the pump speed
- Decrease the vacuum rate
- · Clean the filters
- · Remove crusts and scales
- Use recommended hose size

OBLEM: THE PUMP IS BLOCKED

CAUSE

- · Broken vanes
 - -due to foreign parts
 - -due to faulty lubrication
- · Frozen up pump
- · Damaged drive system

REMEDY

- · Change the vanes
- · Clean filters/elements on the line
- · Check the lubrication pump
- · Warm-up the pump
- · Change the damaged parts

ROSLEM: REDUCED PERFORMANCE

CAUSE

- · 4-Way Valve is in neutral
- Worn vanes
- · Leaking check valve
- · Worn o-rings or seals
- · Leaking gaskets or valves
- · Clogged connecting pipeline
- · Obstructed float ball or air filter
- · Crusted up exhaust manifold
- Undersized hoses
- Rubber connection damaged or obstructed

REMEDY

- · Move handle against the pin
- · Change the vanes
- · Clean the check valve
- · Change the o-rings or seals
- · Change damaged parts
- · Change damaged hoses/pipes
- Dismantle and clean
- · Dismantle and clean
- Use recommended size hose
- Change the connections

PROBLEM: ABNORMAL OIL CONSUMPTION

CAUSE

- · Insufficient Iubrication
- · Excessive oil consumption

REMEDY

- · Adjust the oil pump flow
- · Replace oil seals